



# State Route-248 SR-224 in Park City to SR-32 in Kamas Level One Corridor Study

*June 2007*

UDOT  
Planning Section

# Executive Summary

---

Corridor studies are the map for the Utah Department of Transportation (UDOT) and local governments to identify, evaluate, and set priorities for the statewide transportation system. They provide information to develop regional and statewide long-range transportation plans which, in turn, provide projects to short-range transportation improvement programs.

The State Route-248 (SR-248) Corridor Study begins at milepost 0.0 at the intersection of SR-224 in Park City and ends at the intersection of SR-32 at approximately milepost 14.5 in Kamas. Because of the length of the corridor and the variability of traffic volume and development, it has been divided into three segments. The segments are based upon historic traffic characteristics and the intensity of commercial and residential development.

The main concerns with SR-248 are peak hour congestion and pedestrian concerns in Segments 1 and 2 and peak hour congestion and bicycle lanes for Segment 2. With three schools located very close to each other in Segment 1, Park City has concerns about vehicle and pedestrian access to the schools. This access affects traffic because of the limited travel lanes. While Segment 1 has been striped for bicycle lanes, there is a desire by Park City to have bicycle lanes on SR-248 to US-40.

UDOT has planned to widen SR-248 to four-lanes from SR-224 (four-lanes) through Segment 2 to the Wasatch County line. UDOT plans to widen this 8.22 mile section before the year 2025. Traffic analysis has shown that future travel demand will exceed capacity in this area in 2027 for a two-lane road.

# Table of Contents

---

## 1 IDENTIFICATION OF

|  |          |
|--|----------|
| <b>TRANSPORTATION CORRIDOR STUDY AREA.....</b>                                 | <b>1</b> |
| 1.1 Corridor Description .....   | 1        |
| 1.2 Environmental, Cultural, and Historical Locations within the Corridor..... | 3        |
| 1.3 Historical Perspective of the Corridor .....                               | 3        |
| 1.4 Population, Employment, and Demographics .....                             | 4        |

## 2 ANALYSIS OF EXISTING CONDITIONS..... 5

|  |    |
|--|----|
| 2.1 Analysis Area .....  | 5  |
| 2.1.A Land Use Patterns.....                                   | 5  |
| 2.1.B Traffic Patterns/Characteristics .....                   | 5  |
| 2.1.C Environment .....  | 6  |
| 2.1.D Utilities .....  | 9  |
| 2.1.E Right-of-Way.....  | 10 |
| 2.1.F Safety .....   | 10 |
| 2.1.G Geometric Design.....                                    | 13 |
| 2.1.H Structures .....   | 13 |
| 2.1.I Maintenance .....  | 13 |
| 2.1.J Pavement Condition .....                                 | 14 |
| 2.1.K Alternative Modes and Efficient Intermodal Transfer..... | 14 |
| 2.1.L Access Management Strategies.....                        | 15 |
| 2.1.M Relevant Studies .....                                   | 17 |

## 3 FUTURE CONDITIONS FORECAST ..... 19

|   |    |
|---|----|
| 3.1 Analysis Area .....                         | 19 |
| 3.1.A Land Use Plans and Population Growth..... | 19 |
| 3.1.B Travel Demand Growth .....                | 19 |
| 3.1.C Present and Future Mobility Needs .....   | 21 |

|   |           |
|---|-----------|
| <b>4 PUBLIC INVOLVEMENT .....</b>                             | <b>22</b> |
| 4.1 History of Public Involvement .....                       | 22        |
| 4.2 Outreach Methods and Tools Used.....                      | 22        |
| 4.3 Groups Involved and Summary of Contacts Made.....         | 22        |
| 4.4 Summary of Public Concern.....                            | 22        |
| <b>5 CORRIDOR-WIDE RECOMMENDATIONS .....</b>                  | <b>23</b> |
| 5.1 Take Care of What We Have .....                           | 23        |
| 5.1.A Maintenance and Operations Deficiencies .....           | 23        |
| 5.1.B Right-of-way.....                                       | 23        |
| 5.2 Make the System Work Better .....                         | 23        |
| 5.2.A Access Management .....                                 | 23        |
| 5.2.B Intelligent Transportation Systems.....                 | 24        |
| 5.3 Improve Safety .....                                      | 24        |
| 5.3.A Reduce Crash Rates .....                                | 24        |
| 5.3.B Turn Lanes.....   | 24        |
| 5.3.C Bike Lanes.....   | 24        |
| 5.4 Increase Capacity .....                                   | 24        |
| 5.4.A Travel Demand Management .....                          | 24        |
| 5.4.B Additional Highway Capacity .....                       | 25        |
| <b>6 LIST OF RECOMMENDED PROJECTS AND COST ESTIMATES.....</b> | <b>26</b> |
| <b>7 BIBLIOGRAPHY.....</b>                                    | <b>27</b> |
| <b>8 APPENDIX.....</b>  | <b>28</b> |

# Figures & Tables

---

|  |    |
|--|----|
| Figure 1 – SR-248 Corridor with Milepost Segments .....                            | 2  |
| Figure 2 – Silver King Coalition Mines Co.....                                     | 3  |
| Figure 3 – Historic Traffic Trends .....   | 6  |
| Figure 4 – State Standard Arterial Cross-Section (106 foot right-of-way).....      | 10 |
| Figure 5 – Average and Expected Accident Rates.....                                | 11 |
| Figure 6 – Major Accident Locations (2002 – 2005).....                             | 12 |
| Figure 7 – Cracking at Milepost 1.4 and Milepost 13.9 .....                        | 14 |
| Figure 8 – State Highway Access Management Categories .....                        | 17 |
| Figure 9 – Traffic Forecast for Segment 1.....                                     | 20 |
| Figure 10 – Traffic Forecasts for Segments 2 and 3 .....                           | 20 |
| <br>   |    |
| Table 1 – Population.....  | 4  |
| Table 2 – Employment.....  | 4  |
| Table 3 – Land Use Characteristics .....   | 5  |
| Table 4 – Animal Species in Summit County of S-ESA, SPC, or CS Status .....        | 7  |
| Table 5 – Animal Species in Wasatch County of S-ESA, SPC, or CS Status .....       | 8  |
| Table 6 – Plants in Wasatch County of S-ESA, SPC, or CS Status .....               | 8  |
| Table 7 – Possible Section 4(f) Designations.....                                  | 9  |
| Table 8 – Right-of-Way Width .....   | 10 |
| Table 9 – Expected Accident Rates .....  | 12 |
| Table 10 – Roadway Geometrics .....  | 13 |
| Table 11 – System Preservation Plan (2011–2020).....                               | 14 |
| Table 12 – UDOT, Park City, and Summit County Corridor Preservation Agreement..... | 16 |
| Table 13 – UDOT and Wasatch County Corridor Preservation Agreement.....            | 16 |
| Table 14 – State Highway Access Management Standards .....                         | 17 |
| Table 15 – Signalized Intersections.....   | 18 |
| Table 16 – Projected Traffic Volumes .....   | 21 |
| Table 17 – Planned Major Improvement Project.....                                  | 25 |
| Table 18 – Recommended Improvement Projects .....                                  | 26 |
| <br>   |    |
| Appendix 8A – Annual Average Daily Traffic (AADT) .....                            | 28 |
| Appendix 8B – Accident Data Analysis for SR-248.....                               | 29 |
| Appendix 8C – Accident Data Analysis for SR-248.....                               | 29 |
| Appendix 8D – Cost Estimates for SR-248 Safety Improvement.....                    | 30 |

# 1 IDENTIFICATION OF TRANSPORTATION CORRIDOR STUDY AREA

The Utah Department of Transportation's (UDOT) objective of corridor studies is to develop a best-practice management strategy of the overall statewide transportation system through data collection and analysis of the individual corridors of which it is comprised. Corridor studies investigate conditions of a route and develop possible transportation solutions. They provide an opportunity for UDOT and local government(s) to discuss the corridor and how the corridor does or does not serve their interests or plans. This process may identify strategies in which the corridor can best serve both state and local government interests. Corridor plans are developed from the studies and identify which possible improvements may be needed to improve Utah's transportation system into the future. Corridor plans are the map for UDOT to identify, evaluate, and set priorities for the corridor transportation system. They provide information to develop regional and statewide long-range transportation plans for the 20 plus year horizon which, in turn, provide projects to short-range transportation improvement programs for a six year planning horizon.

Corridor planning is UDOT's program for managing its transportation systems, i.e. the state-administered portion of the overall network, for the long-range plan horizon, and for establishing a vision of corridor needs beyond that. Each corridor study area includes the transportation corridor – the geographic area that influences its performance – in addition to the transportation systems and facilities that make up the corridor.


UDOT has developed, and is continuing to refine, a statewide highway project prioritization system. A number of factors and issues contribute to a project's priority including those related to safety criteria, capacity, pavement management, and bridge sufficiency. This system is used to determine which projects should receive priority status and to assist in establishing a system-wide needs list and long-range plan. Individual corridor plans are one of UDOT's main methods to define corridor and system needs. The proposed projects identified by corridor studies may be primarily focused on preservation, safety, system management, or mobility.

## 1.1 Corridor Description

The SR-248 Corridor Study begins at milepost 0.0 at the intersection of SR-224 in Park City, Utah and extends eastwards to milepost 14.5 at the intersection of SR-32 in Kamas. Due to the length of the corridor and the variability of traffic volume and development, the corridor has been divided into three segments. The segments are based upon historic traffic characteristics and the intensity of commercial and residential development.

- Segment 1 begins at milepost 0.0 and ends at milepost 1.36 at the intersection of Wyatt Earp Way. The volume of traffic and amount of development (commercial and residential) in this segment have historically been higher than in the other two segments.
- Segment 2 begins at milepost 1.36 and ends at milepost 4.65 at the intersection of Brown's Canyon Road. In the past, this segment experienced lower traffic volume and development than Segment 1 but higher values in these areas than Segment 3.
- Segment 3 begins at milepost 4.65 and ends at milepost 14.5 at the intersection of SR-32. Development was limited in this segment, as reflected by historically low traffic volumes.

Figure 1 shows a map of the SR-248 corridor with the three defined milepost segments.



SR-248 is primarily a two lane facility. All portions have shoulders and a center turn lane. There are six traffic signals in the 36.46 miles of roadway, and the posted speed limit is 35 mph in Segments 1 and 45 to 60 mph in Segments 2 and 3.



## 1.2 Environmental, Cultural, and Historical Locations within the Corridor

Park City became famous as a silver mining town and boasts a lively and colorful past. Founded by prospectors in the late 1860's, Park City continued to mine silver until the early 1970's. The mining company, Park City Consolidated Mines, started the ski business in 1963 when they built the first lifts on what was then called Treasure Mountain. The Park City area now has three world class resorts and was a primary venue for the 2002 Winter Olympic Games.

**Figure 2 – Silver King Coalition Mines Co**



*Source: Park City Historical Society and Museum*

Kamas was settled in 1859 and incorporated in 1912. Kamas was known for its lumber and agricultural industries. Plentiful trees in the nearby mountains, an abundance of water for livestock and crops, and fertile soil for the growing of crops, provided the basis for life in this settlement. Today, only about one percent is engaged in lumber or agricultural employment. The average commute to work is 24 minutes.

## 1.3 Historical Perspective of the Corridor

SR-248 was primarily constructed to provide access to and connection between Park City and Kamas. Silver mining was Park City's primary industry until silver prices fell and outdoor recreation replaced mining. Kamas provided important agricultural products such as grain, dairy products, and livestock; and provided lumber products to Park City and the surrounding area. SR-248 was needed to transport these products to Park City and the Salt Lake Valley. Today, SR-248 still serves as the main access and link between Park City and Kamas.



## 1.4 Population, Employment, and Demographics

Park City and Kamas are the only incorporated areas of concern within the study corridor. According to the state population projections shown in Table 1, population in Park City and Kamas is expected to continue growing in the future; indicating that traffic volume on SR-248 will also increase.

| <b>Table 1 – Population</b> |           |                  |       |                  |
|-----------------------------|-----------|------------------|-------|------------------|
| Year                        | Park City | 10 year increase | Kamas | 10 year increase |
| 2000                        | 7,371     |                  | 1,274 |                  |
| 2010                        | 10,987    | 49%              | 1,860 | 46%              |
| 2020                        | 15,339    | 40%              | 2,738 | 47%              |
| 2030                        | 19,776    | 29%              | 3,529 | 29%              |

*Source: Governor's Office of Planning and Budget, February, 2007*

Employment along SR-248 comes from resorts and lodges located within the corridor as shown in Table 2. Due to the nature of the outdoor recreation industry, most of these employment opportunities are seasonal.

| <b>Table 2 – Employment</b>     |                               |
|---------------------------------|-------------------------------|
| Employer                        | Estimated Number of Employees |
| Deer Valley Resort              | 500 - 1000                    |
| The Canyons Resort              | 500 - 1000                    |
| Park City School District       | 500 - 1000                    |
| Park City Mountain Resort       | 250 - 500                     |
| Park City Municipal Corporation | 250 - 500                     |
| Stein Eriksen Lodge             | 250 - 500                     |
| Premier Resorts of Utah, Inc.   | 250 - 500                     |
| Summit County                   | 250 - 500                     |

## 2 ANALYSIS OF EXISTING CONDITIONS

The existing conditions analysis summarizes the existing land use patterns, traffic patterns/characteristics, environment, utilities, right-of-way, safety, geometric design, structures, maintenance, pavement condition, alternative modes and efficient intermodal transfer, access management strategies, and other relevant studies.

### 2.1 Analysis Area

The analysis area begins at milepost 0.0 at the intersection of SR-224 in Park City and terminates at the intersection of SR-32 in Kamas.

#### 2.1.A Land Use Patterns

Segment 1 is characterized by a great deal of commercial and residential development. There are also numerous recreational areas and a few schools in this segment. Land use in Segment 2 is primarily residential with a few commercial establishments and some vacant lands. Most of the land within Segment 3 is vacant; however, there are some low intensity commercial and residential developments and agricultural activity towards the end of the segment in Kamas.

| Table 3 – Land Use Characteristics |            |             |         |            |              |
|------------------------------------|------------|-------------|---------|------------|--------------|
| Segment                            | Commercial | Residential | Schools | Recreation | Agricultural |
| 1                                  | High       | High        | Yes     | No         | No           |
| 2                                  | Low        | Low         | No      | Yes        | No           |
| 3                                  | Low        | Low         | No      | Yes        | Yes          |

#### 2.1.B Traffic Patterns/Characteristics


The major traffic generators along this corridor are schools and residential developments. The few commercial developments within SR-248 also generate some traffic.

Traffic varied from 1985 to 2005 along SR-248 as shown in Figure 3. For example, Segment 1 experienced a 20 percent drop in 1989 and an eight percent drop in 2000 during construction on the route. To compute historic growth rates, it was assumed that traffic growth on this corridor was linear from 1985 to 2005. Segment 1 traffic volume was the highest compared to the other segments. Generally, traffic growth in this segment was ten percent from 1985 to 2005 for an average of 570 additional AADT per year. Segment 1 does experience congestion near the schools because of vehicle and pedestrian traffic.

Historic traffic trends show that traffic volume in Segment 2 was lower than in Segment 1 but higher than in Segment 3. The amount of traffic in Segment 2 grew at a rate of 20 percent per

year (411 AADT per year based on 1985 volume) from 1985 to 2005. Segment 3 experienced the lowest traffic volume compared to the other two segments. Traffic counts in this segment are not available prior to 1990. Traffic growth in Segment 3 from 1990 to 2005 was 16 percent or 260 AADT per year based on 1990 volume.

**Figure 3 – Historic Traffic Trends**



Source: Traffic on Utah Highways

### 2.1.C Environment

The following contains screening level information regarding various environmental topics.

#### Economic

The economy in Summit and Wasatch counties – where SR-248 is located – is primarily tourism based. A large number of resorts and clubs are situated and being constructed along the corridor. According to UDOT's Truck Traffic on Utah Highways 2005 report, truck traffic varied from 15 percent near the intersection of SR-224 in Park City to 39 percent near the intersection of SR-32. Much of this truck traffic is for construction of second homes, resorts, and new development.

#### Air Quality

Summit and Wasatch Counties are not listed as non-attainment or maintenance areas for air quality.

#### Noise

There are many residential and commercial developments close to the corridor in Park City. If widening occurs, noise may become a concern.

Water Quality

Due to the extensive mining from the mid 1800s through the 1970s, water quality is a concern in these areas. Mining took place throughout Park City and, in particular, at the Silver King Mine which is located at the headwaters of Silver Creek. Surface and ground water may contain metals such as zinc, silver, cadmium, copper, lead, and mercury.

Wetlands

According to the National Wetlands Inventory (NWI) maps, there are many locations that have been identified as wetlands along SR-248 in Segments 2 and 3, especially in the Kamas Valley. Much of these wetlands are being used as farmland or pasture for the grazing of animals.

Wildlife

The only identified critical habitat along the SR-248 corridor is approximately seven miles of moose habitat in Segments 2 and 3 from approximately mile post four to mile post ten.

Threatened or Endangered Species

The following three tables contain Summit and Wasatch County animal and plant species that are or have been listed as one or more of the following: Federally-listed or candidate species under the Endangered Species Act (S-ESA), Wildlife species of concern (SPC), and Species receiving special management under a Conservation Agreement in order to preclude the need for Federal listing (CS). The animals and plants listed below are found in Summit or Wasatch Counties but may not be specific to the corridor of SR-248.

| <b>Table 4 – Animal Species in Summit County of S-ESA, SPC, or CS Status</b> |   |              |
|--|---|--------------|
| Common Name  | Scientific Name                         | State Status |
| Bald Eagle   | <i>Haliaeetus Leeucocephalus</i>        | S-ESA        |
| Bluehead Sucker  | <i>Catostomus Discobolus</i>            | CS           |
| Bobolink   | <i>Dolichonyx Oryzivorus</i>            | SPC          |
| Bonneville Cutthroat Trout   | <i>Oncorhynchus Clarkii</i> Utah        | CS           |
| Brown (Grizzly) Bear   | <i>Ursus Arctos</i>                     | S-ESA        |
| Canada Lynx  | <i>Lynx Canadensis</i>                  | S-ESA        |
| Colorado River Cutthroat Trout   | <i>Oncorhynchus Clarkii</i> Pleuriticus | CS           |
| Columbia Spotted Frog  | <i>Rana Luteiventris</i>                | CS           |
| Deseret Mountainsnail  | <i>Oreohelix Peripherica</i>            | SPC          |
| Greater Sage-Grouse  | <i>Centrocercus Urophasianus</i>        | SPC          |
| Leatherside Chub   | <i>Gila Copei</i>                       | SPC          |
| Lewis' Woodpecker  | <i>Melanerpes Lewis</i>                 | SPC          |
| Long-Billed Curlew   | <i>Numenius Americanus</i>              | SPC          |
| Northern Goshawk   | <i>Accipiter Gentilis</i>               | CS           |
| Smooth Greensnake  | <i>Opheodrys Vernalis</i>               | SPC          |
| Three-Toed Woodpecker  | <i>Picoides Tridactylus</i>             | SPC          |
| Western Pearlshell   | <i>Margaritifera Falcata</i>            | SPC          |
| Western Toad   | <i>Bufo Boreas</i>                      | SPC          |

S-ESA (Federally-listed or candidate species under the Endangered Species Act)

SPC (Wildlife species of concern)

CS (Species receiving special management under a Conservation Agreement in order to preclude the need for Federal listing)  
 Source: *State of Utah, Natural Resource, Division of Wildlife Resources, Sensitive Species by County, 2006.*

(There are no plant species listed in Summit County.)

| <b>Table 5 – Animal Species in Wasatch County of S-ESA, SPC, or CS Status</b> |   |              |
|---|---|--------------|
| Common Name   | Scientific Name                         | State Status |
| Bald Eagle  | <i>Haliaeetus Leucocephalus</i>         | S-ESA        |
| Black Swift   | <i>Cypseloides Niger</i>                | SPC          |
| Bluehead Sucker   | <i>Catostomus Discobolus</i>            | CS           |
| Bobolink  | <i>Dolichonyx Oryzivorus</i>            | SPC          |
| Bonneville Cutthroat Trout  | <i>Oncorhynchus Clarkii Utah</i>        | CS           |
| Brown (Grizzly) Bear  | <i>Ursus Arctos</i>                     | S-ESA        |
| Canada Lynx   | <i>Lynx Canadensis</i>                  | S-ESA        |
| Colorado River Cutthroat Trout  | <i>Oncorhynchus Clarkii Pleuriticus</i> | CS           |
| Columbia Spotted Frog   | <i>Rana Luteiventris</i>                | CS           |
| Ferruginous Hawk  | <i>Buteo Regalis</i>                    | SPC          |
| Fringed Myotis  | <i>Myotis Thysanodes</i>                | SPC          |
| Greater Sage-Grouse   | <i>Centrocercus Urophasianus</i>        | SPC          |
| Leatherside Chub  | <i>Gila Copei</i>                       | SPC          |
| Lewis' Woodpecker   | <i>Melanerpes Lewis</i>                 | SPC          |
| Long-Billed Curlew  | <i>Numenius Americanus</i>              | SPC          |
| Northern Goshawk  | <i>Accipiter Gentilis</i>               | CS           |
| Roundtail Chub  | <i>Gila Robusta</i>                     | CS           |
| Short-Eared Owl   | <i>Asio Flammeus</i>                    | SPC          |
| Smooth Greensnake   | <i>Opheodrys Vernalis</i>               | SPC          |
| Three-toed Woodpecker   | <i>Picoides Tridactylus</i>             | SPC          |
| Townsend's Big-Eared Bat  | <i>Corynorhinus Townsendii</i>          | SPC          |
| Western Toad  | <i>Bufo Boreas</i>                      | SPC          |
| Whooping Crane  | <i>Grus Americana</i>                   | S-ESA        |
| Yellow-Billed Cuckoo  | <i>Coccyzus Americanus</i>              | S-ESA        |

Source: *State of Utah, Natural Resource, Division of Wildlife Resources, Sensitive Species by County, 2006.*

| <b>Table 6 – Plants in Wasatch County of S-ESA, SPC, or CS Status</b> |                              |              |
|---|------------------------------|--------------|
| Common Name   | Scientific Name              | State Status |
| Ute Ladies'-Tresses   | <i>Spiranthes Diluvialis</i> | Rare         |

Source: *State of Utah, Natural Resource, Division of Wildlife Resources, Plants.*

#### Flood Plain

The Federal Emergency Management Agency's (FEMA) Flood Insurance Rate Map (FIRM) showed no designated flood zones within the corridor.

#### Wild and Scenic Rivers

According to the National Wild and Scenic Rivers System website, there are no wild and scenic rivers within the vicinity of the corridor.

Historic and Archeological Preservation

Due to the historic mining activities that took place there, Park City has historic structures and old mines such as the Silver King Mine. Typically, cultural resource assessments are performed once a project is identified. However, none are expected along the SR-248 corridor.

Fossil Preservation

No known fossil preservation is being conducted along the corridor.

Hazardous Waste Sites

No known hazardous waste sites have been identified along the corridor.

Visual Impacts

In the locations along SR-248 that might be widened or improved by UDOT, no long-term visual impacts due to construction, widening, or improvements are expected. However, landscaping and restoration of disturbed vegetation during construction will be needed.

Prime and Unique Farmlands

There are six Agricultural Protection Areas totaling approximately 139 acres along SR-248, just west of Kamas.

Section 4(f) Properties

The U.S. Department of Transportation's Section 4(f) law (49 USC 303) states that federal funds may not be approved for projects that use land from a significant publicly owned park, recreation area, wildlife or waterfowl refuge, or any significant historic site. Exceptions may be permitted if it is determined that there is no feasible and prudent alternative to the use of land from such properties and the action includes all possible planning to minimize harm to the property resulting from such use. The following list includes possible Section 4(f) designations:

| <b>Table 7 – Possible Section 4(f) Designations</b> |          |
|---|----------|
| Location  | Milepost |
| Park City High School                               | 0.9      |
| McPolin Elementary School                           | 1.16     |
| Park City Learning Center                           | 1.20     |
| Treasure Mountain International School              | 1.39     |

## 2.1.D Utilities

The three segments of the corridor contain standard utilities common to an urban environment such as communication, natural gas, power, sewer, and water lines. In addition, a Park City




official indicated that the city intends to run a fiber optic cable along SR-248 from milepost 0.0 to milepost 2.0.

### 2.1.E Right-of-Way

In all Segments, most of the land adjacent to SR-248 is privately owned. The right-of-way varies from 100 to 140 feet in Segment 1, 140 to 400 feet in Segment 2, and 220 to 600 feet in Segment 3. Most of SR-248 is a two-lane facility. A constraint that might limit capacity improvements is overhead utility lines that run parallel to the corridor in Segment 1.


| Table 8 – Right-of-Way Width |                   |
|------------------------------|-------------------|
| Segment                      | Right-of-Way (ft) |
| 1                            | 100 -140          |
| 2                            | 140 – 400         |
| 3                            | 220 – 600         |

**Figure 4 – State Standard Arterial Cross-Section (106 foot right-of-way)**



### 2.1.F Safety

Figure 5 shows the average and expected accidents rates over a four year period. Expected accident values for each segment are also shown as provided by UDOT for the years 2002 to 2005. Both average and expected accident rates are reported in number of accidents per million Vehicle Miles Traveled (VMT) per year. For an urban road, expected accident rates depend on the functional class of the roadway, AADT, and the population within close proximity of the roadway. For these reasons, the expected accident rate varies from segment to segment. Segment 1 exceeds the accident rate, but not by much. The reason for a slightly higher accident rate is probably due to lots of pedestrian activity near the schools. Segment 2 is slight below the expected accident rate. However, accident rates can be expected to increase as the traffic volume increases in Segment 2. There are no surprised in Segment 3 where average and expected accident rates are nearly identical.

**Figure 5 – Average and Expected Accident Rates**

The accident rate for Segment 1 decreased every year except for an increase in 2005. Historic traffic trends have shown an increase in traffic volume in Segment 1 from 2002 to 2005. For Segment 2, the accident rate decreased from 2002 to 2003 but increased thereafter. Similarly, traffic volume in Segment 2 declined from 2002 to 2003 but has increased since then. In Segment 3, the accident rate was nearly constant as was the growth in traffic volume.


In Segment 1, more accidents occurred per VMT for three of the four years analyzed than expected for this type of facility and this neighborhood's population. However, exceeded rate was minimal. Segment 2, on the other hand, experienced fewer accidents than expected. The expected accident rate was just slightly exceeded by the actual observed rate in Segment 3 in 2002 and 2005. The values for the expected accident rates plotted in Figure 5 are listed in Table 9.

| <b>Table 9 – Expected Accident Rates</b> |                            |        |        |        |   |   |
|--|----------------------------|--------|--------|--------|---|---|
| Milepost                                 | AADT<br>(Weighted Average) |        |        |        | Functional Class  | Expected Accident Rate (Accidents per million VMT per year) |
|  | 2002                       | 2003   | 2004   | 2005   |   |   |
| Segment 1                                | 16,235                     | 16,363 | 18,472 | 18,838 | Urban-Principal Arterial  | 9.01  |
| Segment 2<br>West of US-40               | 11,294                     | 10,030 | 10,835 | 11,233 | Urban-Principal Arterial (west of US-40) and Rural-Minor Arterial (east of US-40) | 4.56  |
| Segment 3                                | 4,585                      | 4,425  | 5,000  | 5,319  | Rural-Minor Arterial  | 1.70  |

Source: UDOT Traffic & Safety Division

Analysis of accident data has shown that 50 percent of the total accidents in this corridor occurred at the intersections. Approximately 70 percent of the accidents at intersections were right angle collisions between left turning traffic and opposing through traffic. The remaining 30 percent included rear end and T-bone collisions. Of the non-intersection accidents, head-on collisions and accidents involving vehicle roadway departure crashes were equal in occurrence. Two fatalities were reported, one in 2003 in Segment 1, and the other in 2004 in Segment 3. Other accidents resulted in different types of injuries or, possibly, no injuries.

**Figure 6 – Major Accident Locations (2002 – 2005)**



### 2.1.G Geometric Design

#### Roadway

The roadway geometrics (travel lanes, lane widths, center turn lanes, intersection additional turn lanes, channelized right turns, paved shoulders, curb and gutter, and sidewalk) along the corridor are inventoried in Table 10. Each of these features affects capacity and safety of the corridor in various ways. For example, turn lanes are necessary to reduce the conflict between the slow speed turning traffic and the high speed through traffic.

| <b>Table 10 – Roadway Geometrics</b> |           |           |  |
|--------------------------------------|-----------|-----------|--|
| Feature                              | Segment 1 | Segment 2 | Segment 3                                |
| Number of Travel Lanes               | 4         | 2         | 4 (mp 4.65 – 8.22)<br>2 (mp 8.22 – 14.5) |
| Lane Widths (feet)                   | 12        | 12        | 12                                       |
| Center Turn Lanes                    | 100%      | 80%       | 5%                                       |
| Intersection Additional Turn Lanes   | Yes/No    | Yes       | Yes                                      |
| Channelized Right Turns              | Yes       | No        | Yes                                      |
| Paved Shoulders                      | Yes       | Yes       | Yes                                      |
| Curb, Gutter                         | 100%      | 30%       | 2%                                       |
| Sidewalk                             | 100%      | 30%       | 2%                                       |

#### Intersections

No major intersection was identified as having geometric design deficiencies along this route.

### 2.1.H Structures

Two structures have been identified along this corridor:

- 1 US-40 overpass at milepost 3.14
- 2 Pedestrian underpass at Old Landfill Road
- 3 A bridge over an irrigation canal at milepost 14.19

However, a UDOT structures inventory has not been sent to InterPlan.

### 2.1.I Maintenance

One of the maintenance issues identified along SR-248 is cracking at different locations along the corridor. The greatest concentration of cracking is located in Park City and Kamas. Refreshing the striping and slope flattening in the clear zone are also needed at different locations. However, a recent asphalt overlay and re-striping has resolved the cracking and striping concerns.

**Figure 7 – Cracking at Milepost 1.4 and Milepost 13.9**

### 2.1.J Pavement Condition

A 10-year preservation program from 2011 to 2020 is shown in Table 11.

| <b>Table 11 – System Preservation Plan (2011–2020)</b> |              |      |                              |             |
|--|--------------|------|------------------------------|-------------|
| Milepost   | Element ID   | Year | Treatment                    | Cost        |
| 0.0 – 0.793  | 248P-00000   | 2015 | Major Asphalt Rehabilitation | \$1,172,542 |
| 0.0 – 0.793  | 0248P-000.00 | 2015 | Safety Improvement           | \$326,193   |
| 0.793 – 3.125  | 248P-00079   | 2012 | Minor Asphalt Rehabilitation | \$1,128,144 |
| 0.793 – 3.125  | 248P-00079   | 2020 | Minor Asphalt Rehabilitation | \$1,429,100 |
| 3.125 – 14.5   | 248P-00312   | 2017 | Functional Repair            | \$5,731,853 |
| 3.125 – 14.5   | 0C 751       | 2017 | Repair Deck                  | \$100,488   |

Source: UDOT System Preservation Plan 2011-2020

#### Drainage

No drainage issues were observed.

#### Striping and Signing

Lane striping has faded in some areas, particularly in Segment 3, and could be refreshed. Some signs for curves and speed limits have been removed. However, school crossing zones are well maintained in this corridor.

### 2.1.K Alternative Modes and Efficient Intermodal Transfer

Evaluating alternative modes of transportation is important to a functional and efficient transportation system. By reviewing modes beyond traditional highway usage as potential solutions, UDOT can move forward in providing a best-practice transportation system.

- Pedestrian – Pedestrian activity is more prevalent within Park City for Segment 1 and part of Segment 2. Sidewalks have been installed for all of Segment 1. Park City staff has indicated that coordination between them and UDOT regarding the development of

sidewalk should occur. Park City High School, McPolin Elementary, Park City Learning Center, and the Treasure Mountain International School are all located in Segment 1, which creates pedestrian and vehicle traffic. Park City staff has indicated that a pedestrian/bicycle crossing needs to be improved at the eastern end of SR-248 near the schools and that a crossing needs to be installed between Park Avenue and Bonanza Drive.

- Bicycle – Bike lanes have been striped in Segment 1. The other two segments do not have exclusive bike lanes, but there are shoulders. Park City staff has indicated that residents have asked for bike lanes on SR-248 from SR-224 to US-40. UDOT may want to consider striping shoulders to indicate bike lanes because this corridor experiences heavy bike use.
- Transit – Bus numbers one and five of Park City's transit system run on a small portion of SR-248 from SR-224 to Comstock, a distance of approximately one mile.

Planning and coordination should also continue to take place in other systems of transportation including air and truck transportation, pipelines, and railroads. UDOT plays an important coordination role with each of these, particularly in ensuring efficient intermodal transfer with the highway system.

- Aviation – There are no aviation services along SR-248.
- Truck – Most of the truck traffic is generated by the various establishments along the corridor. Trucks use SR-248 to connect between Park City and Kamas. As mentioned earlier, truck traffic varied from 15 percent near the intersection of SR-224 in Park City to 39 percent near the intersection of SR-32 in Kamas.
- Pipeline – There are no signs of any existing pipeline.
- Railroad – There are no highway-rail grade crossings.

### 2.1.L Access Management Strategies

UDOT adopted Administrative Rule R930-6 to accommodate utilities and to control and protect state highway rights-of-way. The state highway access standards contain nine different categories. SR-248 has two access management categories in the study area. They are shown in Figure 8. However, UDOT has cooperative corridor preservation agreements on SR-248 with Park City, Summit County, and Wasatch County for nearly the entire corridor. This forward



thinking arrangement of preservation agreements between UDOT, Park City, Summit County, and Wasatch County will prove beneficial in preserving capacity along the corridor. The Park City and Summit County agreement identifies locations of existing and future traffic signals. Table 12 lists the current and future traffic signal locations in the agreement.


| <b>Table 12 – UDOT, Park City, and Summit County Corridor Preservation Agreement</b> |                            |
|--|----------------------------|
| Location   | Existing or Proposed       |
| Homestake Road   | Proposed                   |
| Bonanza Drive  | Existing                   |
| Park City High School (Approximately midway between Bonanza and Comstock)            | Proposed Pedestrian Signal |
| Comstock Drive   | Existing                   |
| SR-248 at Old Dump Road  | Proposed                   |
| SR-248 IHC Signal (minimum ¼ mile west of US-40 SB off-ramp terminal)                | Proposed                   |

Table 13 lists the future traffic signal locations on SR-248 in Wasatch County.

| <b>Table 13 – UDOT and Wasatch County Corridor Preservation Agreement</b> |
|---|
| Brown's Canyon (Station 112+54)   |
| Deer Mountain's Access (Station 185+25)                                   |
| Tuhaye's Access (Station 348+17)  |

There are current access points along the corridor that do not meet the access management standards. Access management deficiencies are detailed in Section 5.2.A (Corridor Wide Recommendations) of this document. Table 14 shows the underlying standards where the cooperative corridor preservation agreements are not specific.

Figure 8 - State Highway Access Management Categories



Source: UDOT Administrative Rule R930-6, May, 2006

Table 14 – State Highway Access Management Standards

| Category |                       | Minimum Signal Spacing (feet) | Minimum Street Spacing (feet)     | Minimum Access Spacing (feet) | Minimum Interchange to Crossroad Access Spacing (feet) |                                 |                      |
|----------|-----------------------|-------------------------------|-----------------------------------|-------------------------------|--|---------------------------------|----------------------|
|          |                       |                               |                                   |                               | To 1 <sup>st</sup> R-in R-out                          | To 1 <sup>st</sup> Intersection | From last R-in R-out |
| 2        | System Priority Rural | 5,280                         | 1,000                             | 1,000                         | 1,320  | 1,320                           | 1,320                |
| 3        | System Priority Urban | 2,640                         | No Un-Signalized Access Permitted |                               | 1,320  | 1,320                           | 1,320                |
| 4        | Regional Rural        | 2,640                         | 660                               | 500                           | 660  | 1,320                           | 500                  |
| 7        | Community Rural       | 1,320                         | 300                               | 150                           | Not Applicable   |                                 |                      |

Source: Administrative Rule R930-6, UDOT, 2003

## 2.1.M Relevant Studies

### Traffic Signals and Traffic Control Devices

A recent study performed by InterPlan for Park City showed that the SR-248/Bonanza Drive intersection currently operates at an acceptable level of service in the p.m. peak period. Approximately 15 percent of the total number of accidents occurred at unsignalized intersections. Table 15 shows the current signalized intersections along the three Segments.

| <b>Table 15 – Signalized Intersections</b> |          |              |          |              |          |
|--|----------|--------------|----------|--------------|----------|
| Segment 1                                  |          | Segment 2    |          | Segment 3    |          |
| Intersection                               | Milepost | Intersection | Milepost | Intersection | Milepost |
| SR-224                                     | 0.0      | SR-248/US-40 | 3.79     | SR-32        | 14.5     |
| Bonanza Drive                              | 0.48     | SR-248/US-40 | 4.24     |              |          |
| Comstock                                   | 1.11     |              |          |              |          |

### 3 FUTURE CONDITIONS FORECAST

In this section, future conditions for land use, population, travel demand, and mobility needs will be discussed to show potential growth and its impacts on road conditions.

#### 3.1 Analysis Area

The analysis area is from milepost 0.0 at the intersection of SR-224 in Park City and ends at the intersection of SR-32 in Kamas at approximately milepost 14.5

##### 3.1.A Land Use Plans and Population Growth

Future land use along this corridor includes residential, commercial and schools. Park City and County officials indicated that the following developments will take place along SR-248 in the next ten years:


- A hospital and a US Ski Association recreational facility, including a 725 stall parking lot, are planned at approximately milepost 1.3.
- Additional residential development is planned in Segment 1.
- A major commercial development is anticipated to the north of SR-248 at approximately milepost 2.2.
- A recreational facility with a park and ride lot is planned at approximate mile post 3.00 at Gun Club Road.

##### 3.1.B Travel Demand Growth

Future traffic growth on SR-248 is assumed to follow a linear trend as shown in Figures 9 and 10. SR-248 begins as a four-lane highway and decreases to a two-lane highway in the middle of Segment 1. The capacity for a four-lane highway is estimated to be 38,000 vehicles per day. However, Segment 1 is also a two-lane highway. Capacity for the two-lane highway is estimated to be at 20,000 vehicles per day as shown in Figure 9. Volume is approaching capacity for the two-lane portion of Segment 1. Volume for the four-lane portion of Segment 1 is estimated to not exceed capacity over the next 20 years. Except for a passing lane, Segment 2 is mostly a two-lane highway. Part of Segment 3 is a four-lane highway, and the rest is a two-lane highway. For analysis purposes, the capacity for Segments 2 and 3 have been assumed to have a capacity of 20,000 vehicles per day, which is the capacity of a two-lane highway. Figure 10 shows that the capacity in Segment 2 will be at capacity in the 20 year horizon. However, UDOT has plans to widen Segment 2 to a four-lane highway. Therefore, Segment 2 should not reach capacity,


provided that the construction of the four-lanes is completed as planned. Segment 3's capacity will not be exceeded by the year 2030. Table 16 shows the projected traffic volumes for the three Segments.

**Figure 9 – Traffic Forecast for Segment 1**



Source: Traffic on Utah Highways; InterPlan

**Figure 10 – Traffic Forecasts for Segments 2 and 3**



Source: Traffic on Utah Highways; InterPlan

| <b>Table 16 – Projected Traffic Volumes</b> |           |           |           |
|---|-----------|-----------|-----------|
| Year  | Segment 1 | Segment 2 | Segment 3 |
| 2005  | 18,118    | 10,083    | 5,213     |
| 2015  | 24,700    | 14,500    | 8,000     |
| 2030  | 32,000    | 21,000    | 12,000    |

### 3.1.C Present and Future Mobility Needs

The present and future mobility needs of the corridor are largely related to pedestrian traffic in Segment 1 and automobile traffic in all Segments. A discussion could be held between UDOT and the various cities along the corridor to establish the different strategic plans each of them has.



## 4 PUBLIC INVOLVEMENT

The SR-248 Corridor Study begins in Park City at SR-224, travels through Summit County and Wasatch County, and ends in Kamas at SR-32. These four jurisdictions were involved in the study through participating in a corridor drive. No public open house was held.

### 4.1 History of Public Involvement

The corridor drive took place on February 2, 2007. Representatives from Park City, Summit County, Wasatch County, UDOT Region Two, and UDOT Planning participated. During the drive, several comments were made about coordination between UDOT and the jurisdictions and about future maintenance projects. This meeting provided a formal opportunity for communication to occur between the professional city staffs and UDOT Maintenance staff. A representative from UDOT Planning Department was also present. Each jurisdiction provided comments about SR-248.

### 4.2 Outreach Methods and Tools Used

The corridor drive provided a formal opportunity for communication to occur between the professional jurisdictional staffs and UDOT Maintenance and Planning staffs.

### 4.3 Groups Involved and Summary of Contacts Made

Professional staffs were involved from Park City, Summit County, Wasatch County, Kamas, UDOT Region Two, and UDOT Planning.

### 4.4 Summary of Public Concern

Most of the comments centered on the following issues:

- Pedestrian safety along SR-248 in Park City.
- Congestion on SR-248 in Park City.
- Bicycle and pedestrian crossing on SR-248 near the schools and between Park Avenue and Bonanza.
- Access management in Wasatch County in Segment 3.
- Access management standards being too restrictive in Kamas in Segment 3.

## 5 CORRIDOR-WIDE RECOMMENDATIONS

UDOT has four strategic goals upon which their transportation work is centered. The four strategic goals are listed below.

- Take Care of What We Have
- Make the System Work Better
- Improve Safety
- Increase Capacity

The deficiencies that are identified in this report are listed under the four goals.

### 5.1 Take Care of What We Have

#### 5.1.A Maintenance and Operations Deficiencies

Maintenance and operations deficiencies that have been identified include the following:

1. Cracks in the roadway in Park City and Kamas could be sealed.
2. Slope flattening in the clear zone is needed.
3. Refreshing the striping is needed at various locations along the corridor.

#### 5.1.B Right-of-way

The current right-of-way varies between 100 and 600 feet for the length of the corridor. The only area where additional right-of-way may be needed is in Segment 1 where the corridor is 100 feet.

### 5.2 Make the System Work Better

#### 5.2.A Access Management

Access management deficiencies that have been identified include:

- 1 The intersection spacing is shorter than the minimum 150 feet (either between two driveways or from an intersection) at the following locations in Segment 1: mileposts 0.05, 0.12, 0.16, 1.26 and 1.3.
- 2 The spacing between 100 West at milepost 14.37 and SR-32 is less than the 1,000 foot minimum.

Note: Access management standards were adopted after deficiencies such as driveways were built.

### 5.2.B Intelligent Transportation Systems

Intelligent Transportation Systems (ITS) refers to transportation systems which apply emerging hard and soft information system technologies to address and alleviate transportation congestion problems. ITS can be subdivided into three categories: Advanced Traveler Information Systems (ATIS), Advanced Traffic Management Systems (ATMS), and Advanced Vehicle Control Systems (AVCS). The ITS strategies that can help SR-248 function more efficiently include updating signal timing plans and coordinating signalized intersections.

## 5.3 Improve Safety

### 5.3.A Reduce Crash Rates

The rate of accident occurrence on this corridor may be reduced by:

1. Accommodate bikes consistently with UDOT policies and plans.
2. Improving intersection operation by ensuring proper striping, signing, and signal timing.
3. Performing signal warrant analysis at pre-agreed upon unsignalized intersections.
4. Constructing sidewalks in Segment 1 from milepost 0.61 to milepost 1.36.

### 5.3.B Turn Lanes

Center and right turn lanes improve safety by reducing conflicts between motorists at intersections. However, turn lanes increase conflicts between motorists and bicyclists where bike lanes exist. Turn lanes have been provided at most of the intersections. At some major driveways, turn lanes are not striped, but wide shoulders or a center turn lane are available that can be utilized by turning vehicles.

### 5.3.C Bike Lanes

Bike lanes have been striped in Segment 1. The other two segments do not have exclusive bike lanes, but shoulders are present.

## 5.4 Increase Capacity

### 5.4.A Travel Demand Management

Travel Demand Management (TDM) is the planning and implementation of programs that seek to reduce road space demand by influencing travel choices and the amount and timing of travel. TDM aims to encourage more walking, cycling, public transit use, car-pooling, and tele-commuting. The following strategies can help reduce demand for space on SR-248:

1. Accommodate bikes consistently with UDOT policies and plans.
2. Install safe sidewalks in Segment 1 from milepost 0.61 to milepost 1.36 and in Segment 3 from milepost 11.5 to milepost 14.5 by working with Park City to determine best approach to partnering.

#### 5.4.B Additional Highway Capacity

Table 17 lists UDOT's planned improvement project along SR-248. UDOT plans to widen the SR-248 from the end of the existing four lanes in Park City to US-40. Wetlands issues and other environmental considerations may increase costs above the estimated total below.

| <b>Table 17 – Planned Major Improvement Project</b> |             |                   |                     |              |
|---|-------------|-------------------|---------------------|--------------|
| Location  | Year        | Length<br>(Miles) | Improvement<br>Type | Cost         |
| Existing 4-lanes<br>to US-40                        | 2016 - 2025 | 8.22              | Widen to 6-lane     | \$44,000,000 |

Source: UDOT Long Range Transportation Plan 2007-2030

## 6 LIST OF RECOMMENDED PROJECTS AND COST ESTIMATES

The objective of this study was to identify existing deficiencies and future corridor operational, capacity, and geometric characteristics that will become needs in the future. Another objective was to develop a list of improvement projects that will enhance the performance of the corridor. After analyzing the existing conditions and future requirements on SR-248, the recommended improvements are presented in Table 18. This list also includes existing projects contained in the system preservation plan.

| Table 18 – Recommended Improvement Projects   |          |        |      |               |
|---|----------|--------|------|---------------|
| Project   | Begin MP | End MP | Year | Cost Estimate |
| Segment 1   |          |        |      |               |
| 1. Install safety improvements^<br>• Install warning signs<br>• Stripe lanes and shoulders  | 0.0      | 0.68   | 2008 | \$90,000      |
| 2. Install sidewalks^   | 0.61     | 1.36   | 2008 | \$1,000,000   |
| 3. Major asphalt rehabilitation*  | 0.793    | 1.36   | 2012 | \$274,295     |
| 4. Safety improvement*  | 0.0      | 0.793  | 2015 | \$326,193     |
| 5. Major asphalt rehabilitation*  | 0.0      | 0.793  | 2015 | \$1,172,542   |
| 6. Major asphalt rehabilitation*  | 0.793    | 1.36   | 2020 | \$347,469     |
| Segment 2   |          |        |      |               |
| 1. Install safety improvements^<br>• Stripe lanes and shoulders<br>• Install better slope flattening in clear zone<br>• Install warning signs | 1.36     | 3.0    | 2008 | \$524,000     |
| 2. Major asphalt rehabilitation*  | 0.793    | 1.36   | 2012 | \$853,848     |
| 3. Functional repair*   | 3.125    | 4.65   | 2017 | \$768,446     |
| 4. Major asphalt rehabilitation*  | 0.793    | 1.36   | 2020 | \$1,081,630   |
| Segment 3   |          |        |      |               |
| 1. Functional repair*   | 4.65     | 14.5   | 2017 | \$4,963,406   |
| 2. Repair deck*   | 4.65     | 14.5   | 2017 | \$100,488     |

\*UDOT System Preservation Plan 2011-2020

^InterPlan's Estimates Using UDOT's Statewide Standard Item Average Prices, 2006 (See Appendix)

## 7 BIBLIOGRAPHY

American Association of State Highway and Transportation Officials (AASHTO). *A policy on Geometric Design of Highways and Streets*. Washington D.C., 2004.

Utah Department of Transportation (UDOT). *Statewide Standard Item Average Prices and Total Quantities*. 2006.

U. S. Department of Transportation, Federal Highway Administration. *Manual on Uniform Traffic Control Devices (MUTCD)*, Washington D.C., Millennium Edition.

<http://www.utah.gov> Accessed: January 2007.



## 8 APPENDIX

| Appendix 8A – Annual Average Daily Traffic (AADT) |                               |          |                                |          |                                |          |
|---|-------------------------------|----------|--------------------------------|----------|--------------------------------|----------|
| Year  | Segment 1<br>(mp 0.0-mp 1.36) |          | Segment 2<br>(mp 1.36-mp 4.65) |          | Segment 3<br>(mp 4.65-mp 14.5) |          |
|   | AADT                          | Forecast | AADT                           | Forecast | AADT                           | Forecast |
| 1985  | 8125                          |          | 4075                           |          |                                |          |
| 1986  | 8250                          |          | 4125                           |          |                                |          |
| 1987  | 8375                          |          | 4175                           |          |                                |          |
| 1988  | 8390                          |          | 4185                           |          |                                |          |
| 1989  | 8495                          |          | 4240                           |          |                                |          |
| 1990  | 6760                          |          | 2520                           |          | 1435                           |          |
| 1991  | 6950                          |          | 2593                           |          | 1475                           |          |
| 1992  | 7265                          |          | 2713                           |          | 1545                           |          |
| 1993  | 7990                          |          | 3545                           |          | 2100                           |          |
| 1994  | 8615                          |          | 3822                           |          | 2265                           |          |
| 1995  | 9090                          |          | 3867                           |          | 2295                           |          |
| 1996  | 9610                          |          | 7157                           |          | 3000                           |          |
| 1997  | 9990                          |          | 7440                           |          | 3120                           |          |
| 1998  | 12820                         |          | 8030                           |          | 3235                           |          |
| 1999  | 14102                         |          | 8832                           |          | 3558                           |          |
| 2000  | 15690                         |          | 9819                           |          | 3960                           |          |
| 2001  | 14434                         |          | 9663                           |          | 4075                           |          |
| 2002  | 16235                         |          | 10868                          |          | 4585                           |          |
| 2003  | 16363                         |          | 9003                           |          | 4358                           |          |
| 2004  | 18180                         |          | 9727                           |          | 4855                           |          |
| 2005  | 18118                         |          | 10083                          |          | 5213                           |          |
| 2006  |                               | 19073    |                                | 11280    |                                | 5804     |
| 2007  |                               | 20029    |                                | 12476    |                                | 6396     |
| 2008  |                               | 20984    |                                | 13673    |                                | 6987     |
| 2009  |                               | 21939    |                                | 14870    |                                | 7579     |
| 2010  |                               | 22894    |                                | 16066    |                                | 8170     |
| 2011  |                               | 23850    |                                | 17263    |                                | 8762     |
| 2012  |                               | 24805    |                                | 18460    |                                | 9353     |
| 2013  |                               | 25760    |                                | 19656    |                                | 9945     |
| 2014  |                               | 26716    |                                | 20853    |                                | 10536    |
| 2015  |                               | 27671    |                                | 22050    |                                | 11128    |
| 2016  |                               | 28626    |                                | 23246    |                                | 11719    |
| 2017  |                               | 29581    |                                | 24443    |                                | 12311    |
| 2018  |                               | 30537    |                                | 25640    |                                | 12902    |
| 2019  |                               | 31492    |                                | 26837    |                                | 13494    |
| 2020  |                               | 32447    |                                | 28033    |                                | 14085    |
| 2021  |                               | 33402    |                                | 29230    |                                | 14677    |
| 2022  |                               | 34358    |                                | 30427    |                                | 15268    |
| 2023  |                               | 35313    |                                | 31623    |                                | 15860    |
| 2024  |                               | 36268    |                                | 32820    |                                | 16451    |
| 2025  |                               | 37224    |                                | 34017    |                                | 17043    |
| 2026  |                               | 38179    |                                | 35213    |                                | 17634    |
| 2027  |                               | 39134    |                                | 36410    |                                | 18226    |
| 2028  |                               | 40089    |                                | 37607    |                                | 18817    |
| 2029  |                               | 41045    |                                | 38803    |                                | 19409    |
| 2030  |                               | 42000    |                                | 40000    |                                | 20000    |

| <b>Appendix 8B – Accident Data Analysis for SR-248</b>            |        |                |               |             |                |               |              |
|---|--------|----------------|---------------|-------------|----------------|---------------|--------------|
| Segment   |        | 2002           |               |             | 2003           |               |              |
| Beg MP  | End MP | # of Accidents | AADT          | Acc. Rate   | # of Accidents | AADT          | Acc. Rate    |
| 0.0   | 1.07   | 94             | 16,235        | 14.83       | 82             | 16,365        | 12.83        |
| 1.07  | 1.36   | 10             | 16,235        | 5.82        | 2              | 16,360        | 1.15         |
| <b>Weighted Average Values<br/>(Segment 1, mp 0.0 - mp 1.36)</b>  |        |                | <b>16,235</b> | <b>12.9</b> |                | <b>16,363</b> | <b>10.34</b> |
| 1.36  | 3.13   | 8              | 12,255        | 1.01        | 7              | 12,350        | 0.88         |
| 3.13  | 4.53   | 13             | 10,175        | 2.5         | 5              | 7,330         | 1.33         |
| 4.53  | 4.65   | 3              | 10,175        | 6.73        | 1              | 7,330         | 3.11         |
| <b>Weighted Average Values<br/>(Segment 2, mp 1.36 – mp 4.65)</b> |        |                | <b>11,294</b> | <b>1.85</b> |                | <b>10,030</b> | <b>1.15</b>  |
| 4.65  | 9.58   | 15             | 4,585         | 1.82        | 14             | 4,625         | 1.68         |
| 9.58  | 12.04  | 3              | 4,585         | 0.73        | 3              | 4,625         | 0.72         |
| 12.04   | 14.5   | 8              | 4,585         | 1.94        | 5              | 3,825         | 1.46         |
| <b>Weighted Average Values<br/>(Segment 3, mp 4.65 – mp 14.5)</b> |        |                | <b>4,585</b>  | <b>1.58</b> |                | <b>4,425</b>  | <b>1.39</b>  |

| <b>Appendix 8C – Accident Data Analysis for SR-248</b>            |        |                |               |             |                |               |              |
|---|--------|----------------|---------------|-------------|----------------|---------------|--------------|
| Segment   |        | 2004           |               |             | 2005           |               |              |
| Beg MP  | End MP | # of Accidents | AADT          | Acc. Rate   | # of Accidents | AADT          | Acc. Rate    |
| 0.0   | 1.07   | 78             | 18,690        | 10.69       | 101            | 19,375        | 13.35        |
| 1.07  | 1.36   | 5              | 17,670        | 2.67        | 9              | 16,860        | 5.04         |
| <b>Weighted Average Values<br/>(Segment 1, mp 0.0 - mp 1.36)</b>  |        |                | <b>18,472</b> | <b>8.98</b> |                | <b>18,838</b> | <b>11.58</b> |
| 1.36  | 3.13   | 13             | 13,340        | 1.51        | 39             | 13,830        | 4.36         |
| 3.13  | 4.53   | 7              | 7,920         | 1.73        | 12             | 8,210         | 2.86         |
| 4.53  | 4.65   | 4              | 7,920         | 11.53       | 2              | 8,210         | 5.56         |
| <b>Weighted Average Values<br/>(Segment 2, mp 1.36 – mp 4.65)</b> |        |                | <b>10,835</b> | <b>1.97</b> |                | <b>11,233</b> | <b>3.77</b>  |
| 4.65  | 9.58   | 15             | 5,435         | 1.53        | 26             | 5,635         | 2.56         |
| 9.58  | 12.04  | 10             | 4,995         | 2.23        | 7              | 5,180         | 1.51         |
| 12.04   | 14.5   | 2              | 4,135         | 0.54        | 11             | 4,825         | 2.54         |
| <b>Weighted Average Values<br/>(Segment 3, mp 4.65 – mp 14.5)</b> |        |                | <b>5,000</b>  | <b>1.46</b> |                | <b>5,319</b>  | <b>2.29</b>  |

| Appendix 8D – Cost Estimates for SR-248 Safety Improvement         |                              |                 |                          |      |                                 |
|--|------------------------------|-----------------|--------------------------|------|---------------------------------|
| ITEM   | COST                         | UNIT            | QUANTITY PER LINEAR FOOT |      | COST PER LINEAR FOOT OF ROADWAY |
| Concrete Sidewalk (5' wide)  | \$3.80                       | Ft <sup>2</sup> | 5*2*1                    | 10.0 | \$ 38.00                        |
| Sidewalk Untreated Base Course - 1" Max (3"thick)                  | \$0.89                       | Ft <sup>3</sup> | 5*(3/12)*2*1             | 2.5  | \$ 2.23                         |
| Curb and Gutter  | \$36.40                      | Ft              | 2*1                      | 2.0  | \$ 72.80                        |
| Pavement Marking Paint   | \$2.45                       | Ft              | 5*1                      | 5.0  | \$ 12.25                        |
|  | Subtotal                     |                 |                          |      | \$ 125.28                       |
|  |                              |                 |                          |      |                                 |
| Mobilization and Temporary Traffic Control                         | calculated @ 15% of subtotal |                 |                          |      | \$ 18.79                        |
| Contingency  | calculated @ 20% of subtotal |                 |                          |      | \$ 25.06                        |
|  | Subtotal                     |                 |                          |      | \$ 169.12                       |
|  |                              |                 |                          |      |                                 |
| Engineering, construction, management, drainage & utilities        | calculated @ 40% of subtotal |                 |                          |      | \$ 67.65                        |
| Contingency for Price Increases                                    | calculated @ 10% of subtotal |                 |                          |      | \$ 16.91                        |
| TOTAL COST PER LINEAR FOOT   |                              |                 |                          |      | \$ 253.68                       |
| COST OF CONSTRUCTING SIDEWALKS FROM MILEPOST 0.61 TO MILEPOST 1.36 |                              |                 |                          |      | \$ 1,004,580.23                 |

| ITEM  | COST                          | UNIT | QUANTITY PER LINEAR FOOT |      | COST PER LINEAR FOOT OF ROADWAY |
|---|-------------------------------|------|--------------------------|------|---------------------------------|
| Pavement Marking Paint  | \$2.45                        | Ft   | 5*1                      | 5.0  | \$ 12.25                        |
| Slope Flattening  | \$0.36                        | Ft³  | 12*4*1                   | 48.0 | \$ 17.28                        |
|   | Subtotal                      |      |                          |      | \$ 29.53                        |
| Signs (New)   | calculated @ 1.5% of subtotal |      |                          |      | \$ 0.44                         |
| Mobilization and Temporary Traffic Control                          | calculated @ 15% of subtotal  |      |                          |      | \$ 4.43                         |
| Contingency   | calculated @ 20% of subtotal  |      |                          |      | \$ 5.91                         |
|   | Subtotal                      |      |                          |      | \$ 40.31                        |
|   |                               |      |                          |      |                                 |
| Engineering, construction, management, drainage & utilities         | calculated @ 40% of subtotal  |      |                          |      | \$ 16.12                        |
| Contingency for Price Increases                                     | calculated @ 10% of subtotal  |      |                          |      | \$ 4.03                         |
| TOTAL COST PER LINEAR FOOT  |                               |      |                          |      | \$ 60.46                        |
| TOTAL COST OF SAFETY IMPROVEMENT FROM MILEPOST 1.36 TO MILEPOST 3.0 |                               |      |                          |      | \$ 523,558.40                   |

| ITEM  | COST                          | UNIT | QUANTITY PER LINEAR FOOT |     | COST PER LINEAR FOOT OF ROADWAY |
|---|-------------------------------|------|--------------------------|-----|---------------------------------|
| Pavement Marking Paint  | \$2.45                        | Ft   | 5*1                      | 5.0 | \$ 12.25                        |
|   |                               |      |                          |     | \$ 12.25                        |
| Signs (New)   | calculated @ 1.5% of subtotal |      |                          |     | \$ 0.18                         |
| Mobilization and Temporary Traffic Control                          | calculated @ 15% of subtotal  |      |                          |     | \$ 1.84                         |
| Contingency   | calculated @ 20% of subtotal  |      |                          |     | \$ 2.45                         |
|   | Subtotal                      |      |                          |     | \$ 16.72                        |
|   |                               |      |                          |     |                                 |
| Engineering, construction, management, drainage & utilities         | calculated @ 40% of subtotal  |      |                          |     | \$ 6.69                         |
| Contingency for Price Increases                                     | calculated @ 10% of subtotal  |      |                          |     | \$ 1.67                         |
| TOTAL COST PER LINEAR FOOT  |                               |      |                          |     | \$ 25.08                        |
| TOTAL COST OF SAFETY IMPROVEMENT FROM MILEPOST 0.0 TO MILEPOST 0.68 |                               |      |                          |     | \$ 90,053.96                    |